

## CONDITION REPORT: **HYDRAULIC EXCAVATOR**

MAKE:	KOMATSU	YEAR:	2012	SMR:	3577
MODEL:	PC200-8	SERIAL NUMBER:	354447	LOCATION:	SIGMA INTL
BUCKET BRAND:	HENSLEY	HYDRAULIC KIT:	YES	3RD VALVE	YES
BUCKET CAPACITY:	1.34 YR3	THUMB:	N/A	SPECIALTY	N/A
ARM LENGTH:	9' 7"	SHOES WIDTH:	700 MM		

■ EXCELLENT

■ GOOD

■ FAIR

■ N/A

GENERAL	RECEPTION	COMMENTS/ACTIONS	PRE-DELIVERY
Paint	<span style="color: yellow;">■</span>		
Glass / Mirrors / Windows	<span style="color: green;">■</span>	Right cab mirror broken. Front lower cab glass broken.	
Work lamps	<span style="color: yellow;">■</span>		
Counterweight	<span style="color: yellow;">■</span>		
Hood / Grills / Fenders	<span style="color: yellow;">■</span>		
Guards / Covers / Steps / Ladder	<span style="color: yellow;">■</span>		
Battery box / Compartment	<span style="color: yellow;">■</span>		
SAFETY	RECEPTION	COMMENTS/ACTIONS	PRE-DELIVERY
Horn	<span style="color: yellow;">■</span>		
Travel Alarm	<span style="color: yellow;">■</span>		
Parking Brake	<span style="color: yellow;">■</span>		
CAB	RECEPTION	COMMENTS/ACTIONS	PRE-DELIVERY
Seat / Armrests / Seat Belt	<span style="color: green;">■</span>		
Hour-meter	<span style="color: yellow;">■</span>		
Monitor Panel / Bottoms / Switches	<span style="color: yellow;">■</span>		
Air Conditioner	<span style="color: blue;">■</span>	Not working.	
Radio AM / FM	<span style="color: green;">■</span>		
Windshields / Wiper / Wiper Motor / Reservoir	<span style="color: green;">■</span>		
Joysticks / Pedals	<span style="color: green;">■</span>		
Door Locker	<span style="color: green;">■</span>		
Interior Lights	<span style="color: yellow;">■</span>		
Floor Mat	<span style="color: yellow;">■</span>		
ENGINE	RECEPTION	COMMENTS/ACTIONS	PRE-DELIVERY
Exhaust Smoke	<span style="color: yellow;">■</span>		
Blow-by Pressure	<span style="color: magenta;">■</span>		
Leaks (Oil / Fuel / Coolant)	<span style="color: green;">■</span>	Not leaks	
Noises	<span style="color: yellow;">■</span>	No noises	
Turbo / Blower	<span style="color: green;">■</span>		
Belts / Pulleys	<span style="color: green;">■</span>		
Exhaust System	<span style="color: green;">■</span>		

### RECEIVING INSPECTION

Date:

Inspected by:

Signature: \_\_\_\_\_

### PRE-DELIVERY INSPECTION

Date:

Inspected by:

Signature: \_\_\_\_\_

COOLING SYSTEM	RECEPTION			COMMENTS/ACTIONS	PRE-DELIVERY		
Radiator Panel		■					
Coolant (Color / Level)		■		Level to be completed.			
Water Pump		■					
Fan		■					
Hoses		■					
ELECTRICAL SYSTEM	RECEPTION			COMMENTS/ACTIONS	PRE-DELIVERY		
Starter		■					
Alternator		■					
Batteries / Cables			■	Batteries in bad conditions, not working properly.			
Wiring		■					
HYDRAULIC SYSTEM	RECEPTION			COMMENTS/ACTIONS	PRE-DELIVERY		
Pumps	■						
Valves	■						
Hydraulic Tank	■						
Hydraulic Hoses		■					
Auxiliary Hydraulic Plumbing		■					
Swing Motor	■						
Travel Motors		■					
Boom Lift Cylinders	■						
Arm Cylinder			■	Small leak.			
Bucket Cylinder	■						
CHASSIS	RECEPTION			COMMENTS/ACTIONS	PRE-DELIVERY		
Bucket Teeth / Adapters		■		Bucket teeth 80% life remaining.			
Boom Condition	■						
Arm Condition	■						
Boom Base Pin & Bushings		■		70% Life remaining.			
Boom to Arm Pin & Bushings		■		70% Life remaining.			
Arm to Bucket Pin & Bushings		■		80% Life remaining.			
Arm to Coupler Pin & Bushings			■				
Turn Table Bearings / Ring Gear / Pinions		■					
Bottom Covers		■					
Roller Frames		■					
UNDERCARRIAGE	RECEPTION			COMMENTS/ACTIONS	PRE-DELIVERY		
Track Tensioners (Brand / [%] Life Remaining)		■					
Carrier Rollers (Brand / [%] Life Remaining)		■		80% Life remaining.			
Top Rollers (Brand / [%] Life Remaining)		■		75% Life remaining.			
Sprockets (Brand / [%] Life Remaining)		■		85% Life remaining.			
Idlers (Brand / [%] Life Remaining)		■		90% Life remaining.			
Links, Pins & Bushings (Brand / [%] Life Remaining)	■			85% Life remaining.			
Pad, Grousers [%] Life Remaining		■		85% Life remaining.			
Pins / Bushings Turned [%] Life Remaining				Not turned			

CONDITION REPORT:  
**HYDRAULIC EXCAVATOR**  
KOMATSU PC200-8

**2012 // Komatsu // Ref #: 354447**

**DESCRIPTION:**

- EROP Cab with A/C hyd kit.
- 18'-8" (5,700 mm) boom.
- 9'-6" (2,900 mm) stick.
- Hensley Heavy Duty Bucket with capacity: 1,34 yd<sup>3</sup>.
- 700 mm shoes.

**CHARACTERISTICS:**

Used | 0 hours | Sigma Intl

